Q-341

SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.FordBBAS.com (click "Contact Us")
Toll-free: (877) 840-4338

QVM BULLETIN: Q-341 DATE: 21 / SEPT / 2011

SUPERDUTY POWER DISTRIBUTION BOX COVER

REVISION	UPDATE	REVISION DATE
Q-341	Initial release	21/SEPTEMBER/ 2021

MODEL(S) AFFECTED:
2017 Model Year to Present Super Duty

ISSUE / DESCRIPTION:
Warranty claims for damage to the Power Distribution Box due to water intrusion are being received as the cover to the Power Distribution Box is not being properly re-installed during vehicle upfits. **This is not a warrantable condition.** ***Vehicle Upfitters must ensure that, if the Power Distribution Box cover is removed as part of a vehicle upfit, the cover must be re-installed correctly in order to prevent water intrusion and potential damage to the vehicle electrical system.***

Example of incorrect latching of the PDB cover.

Example of correct PDB cover latching





Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the Ford Body Builders Advisory Service as shown in the header of this bulletin.